Order - No.: DD+DIS355.00E



1 Piece UG2DA MA1

December 2000

Field Service Bulletin No. 14 for

ADC Solo

Type 5155 / 100

Classification			When		
Safety relevant	Reliability	New function	Immediately	Next service	As required
	Х			Х	

Software Patch SOLG1108 is available now

Order Number:

CM+9.5155.1050.4 SOL_1108 + Patch SOLG1108

Scope of Delivery

- SOL 1108
 - 4 floppy disks (1 x 'HD formatter' floppy (boot floppy), 3 x application program floppies)
- SOLG1108: 1 floppy disk
- 1 empty floppy disk
- 1 upgrade instructions (DD+DIS323.00E)
- 1 instructions for the adjustment of the side wall/cassette unit (DD+DIS197.99E)

What is new in Patch SOLG1108

 Patch SOLG1108 solves the sporadic error message 247B0 "repeated checks of the erasure lamps' current flow".



SOLG1108 includes all the previous patches of version SOL_1108.